



## PRODUCT CHANGE NOTIFICATION

Date: September 10, 2015  
PCN: PCN LEDIL 107

---

**Subject: PCN 107 - Discontinuation of duplicate assemblies**

**Description:** As part of our continuous improvement process regarding the logistics and quality of our products LEDiL is discontinuing LISA2 products with duplicate product structure. Discontinued products share the same components and structure with products that are replacing them so there are no changes on optical performance or specifications of the affected products.

**Time line:** This change is valid immediately

**Changes:**

DISCONTINUED PRODUCT	REPLACED BY
FP11000_LISA2-WW-PIN	FP10994_LISA2-WW-PIN
FP11057_LISA2-RS-PIN	FP11056_LISA2-RS-PIN
FP11079_LISA2-W-CLIP	FP11073_LISA2-W-CLIP
FP11080_LISA2-WW-CLIP	FP11074_LISA2-WW-CLIP
FP11855_LISA2-O-90-PIN	FP11853_LISA2-O-90-PIN
FP10998_LISA2-M-PIN	FP10992_LISA2-M-PIN
FP11123_LISA2-O-CLIP	FP11122_LISA2-O-CLIP
FP11087_LISA2-RS-CLIP	FP11086_LISA2-RS-CLIP
FP10999_LISA2-W-PIN	FP10993_LISA2-W-PIN
FP11078_LISA2-M-CLIP	FP11072_LISA2-M-CLIP
FP11954_LISA2-WWW-PIN	FP11951_LISA2-WWW-PIN
FP11860_LISA2-O-90-CLIP	FP11858_LISA2-O-90-CLIP
FP11127_LISA2-O-PIN	FP11126_LISA2-O-PIN
FP11955_LISA2-WWW-CLIP	FP11952_LISA2-WWW-CLIP

**Contact information:** Tero Mäkinen  
LEDIL Oy  
Salorankatu 10  
24240 SALO, FINLAND  
tero.makinen@ledil.com