



PRODUCT CHANGE NOTIFICATION

Date: September 19, 2016
PCN: PCN LEDIL 126 a, b, c

Subject: PCN 126.a – EOL notice

Description: As part of our continuous quality improvement process LEDiL is planning to obsolete four-screw versions of 2X2MX family in order to remove possible risk of compromised ingress protection in cases where the lens is used close or over its maximum temperature limits.
LEDiL does not recommend four-screw versions to be used in new designs anymore, and will upgrade 2X2MX product family to use eight screws as we already do in 2X2MXS products.
All current beams will be available in eight-screw versions later this year and all new beams will come with eight screws by default.

This change will cause minor changes into recommended PCB design, as we need to reduce PCB outline dimensions 1,5 mm from each side to make room for additional screw towers and the modified gasket. You can find new REV2 design file as an attachment. The LED layout will remain unchanged.

Time line: Eight-screw versions for existing 2X2MX beams are targeted to be available in November 2016, and LEDiL offers last buy opportunity for the four-screw versions until November 30th 2017.

Affected products: CS14840_HB-2X2MX-M
CS14713_HB-2X2MX-W
CS14839_HB-2X2MX-WWW
CS14632_STRADA-2X2MX-DWC
CS14764_STRADA-2X2MX-VSM
CS14841_STRADA-2X2MX-SCL
CS15389_STRADA-2X2MX-T2-S

Changes: Products will be replaced as follows.

CS14840_HB-2X2MX-M → **CS15767_HB-2X2MX-8-M**
CS14713_HB-2X2MX-W → **CS15759_HB-2X2MX-8-W**
CS14839_HB-2X2MX-WWW → **CS15765_HB-2X2MX-8-WWW**
CS14632_STRADA-2X2MX-DWC → **CS15751_STRADA-2X2MX-8-DWC**
CS14764_STRADA-2X2MX-VSM → **CS15763_STRADA-2X2MX-8-VSM**
CS14841_STRADA-2X2MX-SCL → **CS15761_STRADA-2X2MX-8-SCL**
CS15389_STRADA-2X2MX-T2-S → **CS15769_STRADA-2X2MX-8-T2-S**

Contact information:

Olli Laakkio
Product Manager
Salorankatu 10
24240 SALO, FINLAND
olli.laakkio@ledil.com

Veijo Isojunno
Product Manager
Salorankatu 10
24240 SALO, FINLAND
veijo.isojunno@ledil.com

Olga Cherepenina
Product Marketing Manager
Salorankatu 10
24240 SALO, FINLAND
olga.cherepenina@ledil.com



PRODUCT CHANGE NOTIFICATION

Date: September 19, 2016
PCN: PCN LEDIL 126 a, b, c

Subject: PCN 126.b - Change of packaging quantities

Description: As part of our continuous improvement process regarding the logistics LEDiL has changed the packaging quantities of following products.

Time line: This change is valid immediately.

Changes:

AFFECTED PRODUCT	Old BOX qty.	Upd. BOX qty.	Old MPQ	Upd. MPQ	Old MOQ	Upd. MOQ	Old Gr2	Upd. Gr2	Old Gr3	Upd. Gr3
CA14433_MINNIE-LT-W	540	720	45	45	90	90	540	720	10260	10080
CA14434_MINNIE-LT-M	540	720	45	45	90	90	540	720	10260	10080
CA14941_MINNIE-LT-M-PIN	540	720	45	45	90	90	540	720	10260	10080
CA14942_MINNIE-LT-W-PIN	540	720	45	45	90	90	540	720	10260	10080
CA13949_REBECCA-RGB	320	288	32	32	96	96	320	288	10240	10080
CA14416_REBECCA-RGB-HLD	320	288	32	32	96	96	320	288	10240	10080
C13910_REBECCA-RGB-HLD	320	288	32	32	96	96	320	288	10240	10080
F11947_JULIA-A	3000	4500	500	500	1000	1000	3000	4500	12000	13500
CS14839_HB-2X2MX-WWW	152	136	8	8	24	24	384	408	10112	10064
C14832_HB-2X2MX-WWW	152	136	8	8	24	24	384	408	10112	10064
C15028_FLORENTINA-4X1-SHD	184	184	2	2	80	72	1104	1104	10120	10120
C15690_FLORENTINA-4X1-SHD-WHT	184	184	2	2	80	72	1104	1104	10120	10120
CC14855_FLORENTINA-RS	*	*	3	4	30	32	200	200	2000	2000
CC14999_FLORENTINA-SS	*	*	3	4	30	32	200	200	2000	2000
CC15000_FLORENTINA-M	*	*	3	4	30	32	200	200	2000	2000
CC15001_FLORENTINA-O	*	*	3	4	30	32	200	200	2000	2000
CC15002_FLORENTINA-D	*	*	3	4	30	32	200	200	2000	2000
CC15251_FLORENTINA-WW	*	*	3	4	30	32	200	200	2000	2000
FC15003_FLORENTINA-W	*	*	3	4	30	32	210	200	2100	2000
FC15004_FLORENTINA-WW	*	*	3	4	30	32	210	200	2100	2000
C14446_FLORENTINA-SHD	100	100	1	1	30	32	200	200	2000	2000

*assembly parts to be delivered separately

Contact information:
Olli Laakkio
Product Manager
Salorankatu 10
24240 SALO, FINLAND
olli.laakkio@ledil.com

Veijo Isojunno
Product Manager
Salorankatu 10
24240 SALO, FINLAND
veijo.isojunno@ledil.com

Olga Cherepenina
Product Marketing Manager
Salorankatu 10
24240 SALO, FINLAND
olga.cherepenina@ledil.com



PRODUCT CHANGE NOTIFICATION

Date: September 19, 2016
PCN: PCN LEDIL 126 a, b, c

Subject: PCN 126.c – Change in product mechanics

Description: As part of our continuous improvement process regarding the quality of our products, LEDiL is planning to change LARISA-CLIP design to improve fastening to the PCB.

Time line: LEDiL will deplete existing stock before making the change


Affected products: C12907_LARISA-HOLDER-CLIP8
C12908_LARISA-HOLDER-CLIP16
C13124_LARISA-HLD-B-CLIP16
C15049_LARISA-HLD-B-CLIP16-WHT

Included in following assemblies:


CP13665_LARISA-RZ-CLIP8
CP12942_LARISA-O-CLIP8
CP12944_LARISA-W-CLIP8
CP12946_LARISA-WW-CLIP8
CP12938_LARISA-RS-CLIP8
CP12940_LARISA-M-CLIP8
CP13666_LARISA-RZ-CLIP16
CP12943_LARISA-O-CLIP16
CP12945_LARISA-W-CLIP16
CP12947_LARISA-WW-CLIP16
CP12939_LARISA-RS-CLIP16
CP12941_LARISA-M-CLIP16
CP15460_LARISA-O-90-CLIP16
CP13134_LARISA-RS-CLIP16
CP13135_LARISA-M-CLIP16
CP13136_LARISA-O-CLIP16
CP13137_LARISA-W-CLIP16
CP13138_LARISA-WW-CLIP16
CP13667_LARISA-RZ-CLIP16

Changes: Clip design has been made more robust to improve fastening on the PCB. The mechanical compatibility remains unchanged.

Old version:



New version:



Contact information:
Olli Laakkio
Product Manager
Salorankatu 10
24240 SALO, FINLAND
olli.laakkio@ledil.com

Veijo Isojunno
Product Manager
Salorankatu 10
24240 SALO, FINLAND
veijo.isojunno@ledil.com

Olga Cherepenina
Product Marketing Manager
Salorankatu 10
24240 SALO, FINLAND
olga.cherepenina@ledil.com